

CASHWOOL® PAINT

Nm. 2/30

100% (WV) lana extrafine (19,5µ)



“Solidità colori”: secondo le norme Woolmark.
Eventuali esigenze particolari andranno specificate all'atto dell'ordine.

“Quantità ottimali”: scatole da Kg. 24.

Per colli di peso inferiore vengono applicati supplementi per minimi.

IMPIEGO

Nm 2/30

| | | |
|-----------------|------------------|----------|
| Cotton 21-24 GG | Rett. Fin. 12-14 | a 1 capo |
| Cotton 12 GG | Rett. Fin. 7-8 | a 2 capi |

FINISSAGGIO

Con un semplice stiro e con abbondante vaporizzo si ottiene un ottimo aspetto della maglia.

Per esaltare al meglio la sofficità e la gonfiezza del filato si consiglia una leggera follatura in acqua per 3-5 minuti con ammorbidente al 2-3% sul peso della merce, ad una temperatura non superiore a 35° gradi.

Centrifugare, asciugare in tumbler a 80° gradi in 15 minuti senza essicare. Finire stirando con abbondante vapore.

CASHWOOL® PAINT

Nm. 2/30

100% (WV) extrafine wool (19,5µ)



“Colour fastness”: as per Woolmark specifications.
Any other special fastness should be expressly request.
“Optimum quantity” package of about 24 Kgs.
An extra charge will be required for cartons of inferior weight.

KNITTING

Nm 2/30

| | | |
|----------------------|--------------------|-------|
| F.F. Cotton 21-24 GG | Flat Machine 12-14 | 1 Ply |
| F.F. Cotton 12 GG | Flat Machine 7-8 | 2 Ply |

FINISHING

A normal pressing with a lot of steam will give an excellent regular effect. To enhance softness and bulkiness of the yarn, we suggest a light milling for 3-5 minutes in water using a wool softener in the ratio of 2-3% of the garment's weight, at a temperature of less than 35°C.

After milling, centrifuge and tumbler dry at a temperature around 80°C for 15 minutes. Avoid overdrying garments, press with a lot of steam.



INDEX

| | | | |
|--------|----|--------|----|
| 530112 | 4B | 530135 | 3B |
| 530114 | 3D | 530144 | 2C |
| 530116 | 2E | 530147 | 4C |
| 530118 | 2D | 530187 | 2B |
| 530119 | 3E | 530188 | 1A |
| 530120 | 1C | 530189 | 1B |
| 530121 | 1E | 530190 | 3A |
| 530130 | 2A | 530191 | 4A |
| 530133 | 4E | 530192 | 1D |
| 530134 | 3C | 530193 | 4D |

1


2

3


4



530188



530130



530190




530191




530189



530187



530135




530112



530120



530144




530134



530147




530192




530118



530114




530193



530121



530116



530119



530133

A

B

C

D

E